

June 27, 2000



Electricity Distribution Rate Handbook **Correction**

Page 7-9

Revision 0

Issued: March 9, 2000

The following should be added to Table 7-2 "Cause of Service Interruption":

Code

9

Cause

Adverse Environment

Customer interruptions due to equipment being subjected to abnormal environments such as salt spray, industrial contamination, humidity, corrosion, vibration, fire or flooding.