Filed: 2003-09-18 RP-2003-0044 Exhibit J8 Tab 12 Schedule 17 Page 1 of 1

## Wirebury Connections Inc. INTERROGATORY #17

2
3

1

## **Interrogatory**

4

Networks contends that overlapping service areas will create operating inefficiencies and the need for extensive safety protocols.

6 7 8

Reference: p. 19 L25-30

9 10

11

a) How does Networks deal with the interaction and interconnection of its service territory with the 195 bordering LDC service territories? How many safety protocols are currently in place?

12 13 14

b) Are there safety issues in Networks' operations with over 88 new distributors being acquired recently or have the differences in operating practices been fully mitigated by proper procedures and protocols.

16 17 18

19

20

15

c) Why could the same processes/protocols not be used in the case of overlapped service areas? Please explain your response in detail indicating the degree of incompatibility within Networks and how it has been or will be mitigated and the ability to use the same mitigation approach for overlapping service areas.

212223

## Response

242526

(a) The protocols Networks normally has in place for LDCs served by Networks' distribution system are:

272829

30

31

• Operating protocols

• Connection Agreements

• Safety protocols and rules as established under the Occupational Health and Safety Act.

323334

(b) No, all operations and assets have been fully integrated into Networks' system.

35 36

37

38

39

40

(c) The existing overlapping is currently very limited. The current protocols are adequate for these circumstances, however, if the level overlapping were increased, Networks believes additional protocols would need to be established. Networks believes that expanding overlapping service areas will lead only to increased complexity, safety problems, and inefficiency. Please see Networks' Exhibit J8-10-14.