

Recommendations draft

- CSA C22.3 No.9
 - The OEB Working Group asks the ESA to confirm that inverters certified to UL 1741 SA (2016) will be considered to meet the requirements of CSA C22.3 No.9.
 - Inverters that are approved to UL 1741 SA (2016) do not satisfy all interconnection requirements in CSA standard C22.3 No.9
 - Applies to situations where the LDC would require inverters that meet CSA standard (i.e. allows UL1741 certified inverters to be used until C22.2 No. 107.1 is updated)
 - inverters CSA standard C22.2 No. 107.1 is expected to be updated in 2020/2021 and will reference CSA C22.3 No. 9 standard for interconnection requirements

Recommendations draft

ESA is considering OEB Working Group request, additional information is required:

- Clarification if only mandatory interconnection tests in UL1741 SA (2016) are required or additional OPTIONAL control/tests are needed.
- Are all inverters required to meet UL1741 SA (2016) requirements or this direction applies only to inverters that are injecting (exporting) into distribution system?
- Specify the date (period) for the OEB Working group request for accepting approval requirements to the UL standard for inverters